## Ohaus Corporation Application Note

Model: .. Defender Indicators T31P and T31XW

Description: ...... Counting Mode setup & use

## Ohaus Corporation Application Note

Model: .. Defender Indicators T31P and T31XW

Description: ........... Counting Mode setup & use

## Ohaus Corporation Application Note

Model: .. Defender Indicators T31P and T31XW

Description: ...........Counting Mode setup & use

## To reset the APW when changing to another part

- 1. Clear the pan
- 2. Press and hold the "Function-Mode" button until the display shows "Count" then release.
- 3. "Clr.PW" will be displayed.
- 4. Press and release "Yes"
- 5. "Put xxx" will be displayed
- 6. Continue as above